



Subject: Transmission Control Module (TCM) Part Number Change - Endurant HD, PACCAR, and Procision MD

Document Number: TAIB-0991

Date: March 29, 2021

Issue Description: New content TCM service kits were obsoleted March 1, 2021 for Endurant HD, PACCAR, and Procision MD.

Containment/Corrective Action: REMAN TCM Service Kits were released March 1, 2021.

Affected Models/Population:

- Endurant HD
- PACCAR
- Procision MD

Field Strategy: Obsolescence of new content TCM part numbers and the release of REMAN TCM part numbers March 1, 2021.

Endurant

Obsoleted Part Number	REMAN Part Number	Core	REMAN Description
K-4398	K-4398R	\$500	REMAN TCM ASSY KIT Endurant HD 12-Speed
K-4398-PAC	K-4398R-PAC	\$500	
K-4487	K-4487R	\$500	REMAN TCM ASSY KIT Endurant HD 11-Speed
K-4487-PAC	K-4487R-PAC	\$500	
N/A	K-4517R	\$500	REMAN TCM ASSY KIT Endurant HD 12-Speed CNG / Cummins
	K-4517R-PAC		

PACCAR Only

Obsoleted Part Number	REMAN Part Number	Core	REMAN Description
K-4354-PAC	K-4354R-PAC	\$500	REMAN TCM ASSY KIT PACCAR 12 Speed

Procision

Obsolete Part Number	REMAN Part Number	Core	REMAN Description
K-4266	K-4266R	\$500	REMAN TCM ASSY KIT (EDCO-XX107A)
K-4269	K-4269R	\$500	REMAN TCM ASSY KIT (EDCO-XX107A-P)
K-4274	K-4274R	\$500	REMAN TCM ASSY KIT (EDCO-XX107A-B)

Warranty Information:

N/A

The material contained in this bulletin is product improvement information. Eaton Corporation is not committed to, or liable for, canvassing existing products. FSUD: 2021-FSUD-4266