Service Bulletin - Product





Subject: Introduction of Transmission Parts Book – Endurant HD


Document Number: PBIB-0001

Date: October 3, 2022 Updated:

Issue Description:

An Endurant HD Transmission Parts Book (TRPB0950) has been developed to provide a stand-alone resource to improve the service parts and kits lookup customer experience.

Endurant HD Product Page, screen shot:



Affected Models/Population:

Endurant HD

- EEO-xxF112C
- EE-17F111B
- EHD-14112C-N

Service Bulletin – Product

Field Strategy:

How to access:

1. Select link: <u>TRPB0950 – Product Information Library version</u>

Or

1. Select link: TRPB0950 – PDF version

Or

- 1. Navigate to www.eatoncummins.com
- 2. Select "Products".
- 3. Select "Transmissions".
- 4. Scroll down and select "Endurant HD automated transmission".
- 5. Select "Resources".
- 6. Select "Parts Book" (Production Information Library version).

Or

- 1. Navigate to www.eatoncummins.com
- 2. Select "Products".
- 3. Select "Transmissions".
- 4. Scroll down and select "Endurant HD automated transmission".
- 5. Select "Resources".
- 6. Scroll down and select "Service and troubleshooting".
- 7. Select "Endurant HD Automated Transmission Parts Book" (PDF version).

NOTICE: Always reference the latest electronic version of this document to ensure accurate service information.

Warranty Information:

Information only.

The material contained in this bulletin is product improvement information. Eaton Corporation is not committed to, or liable for, canvassing existing products. FSUD: 2022-FSUD-4449